

New Product Development

We're not just a complete
Exhaust Hardware provider,
we're problem solvers.

**DESIGN MAKES
THE DIFFERENCE**

31977 Repair Pipe




Image not scale

IN STOCK

USES GASKET 13095

2000-05 Ford Taurus 3.0L DOHC Vin S
2000-07 Ford Taurus 3.0L OHV Vin U
2000-05 Mercury Sable 3.0L DOHC Vin S
2000-07 Mercury Sable 3.0L OHV Vin U



Made In USA



ni

nickson industries, inc.
336 Woodford Ave., Plainville, CT 06062
1-800-243-0126
www.nickson.com

NPD31977