

New Product Development

3 Bolt Flange With Pipe & O2 Sensor Bung
 GM Trucks:
 1999-2007 4.3L Right Side
 1999-2007 4.8L & 5.3L Right Side
 1999-2007 some 6.0L 8.1L Left/Right Side



USES FLANGE 15051

**USES GASKET 13323
 OR CRUSH RING 13329**

**ni Number
 15900**

3 Bolt Flange With Pipe & O2 Sensor Bung
 GM Trucks:
 1999-2005 4.3L Left Side
 1999-2001 4.8L & 5.3L Left Side



USES FLANGE 15050

**USES GASKET 13323
 OR CRUSH RING 13329**

**ni Number
 15901**

3 Bolt Flange With Pipe & O2 Sensor Bung
 GM Trucks:
 Mid 2007 & up 4.3L, 4.8L, & 5.3L Left Side
 Mid 2007 & up 6.0L & 8.1L Left Side





Angled Pipe

USES FLANGE 15050

**USES GASKET 13323
 OR CRUSH RING 13329**

**ni Number
 15902**



Made in USA



nickson industries, inc.
 336 Woodford Ave., Plainville, CT 06062
 1-800-243-0126
 www.nickson.com
 NPD 159xx